

TIMBER PRESERVATION SPECIALISTS LIMITED

ERADICATORS OF WET ROT

DRY ROT

WOODWORM AND RISING DAMP

ASTOR HOUSE, LICHFIELD ROAD, FOUR OAKS, SUTTON COLDFIELD, WARWICKSHIRE

REPORT TO: Blinkhorn & Company, 12, Vine Street, Evesham, Worcz.

INSPECTION REPORT & ESTIMATE

ADDRESS OF PROPERTY The Manor House, High Street SURVEY No. 1183/WM/MS Badsey Woros.

30th September, 1970

Dear Sirs.

At your request the above mentioned property has been inspected by our Timber Infestation Surveyor and we are pleased to submit the following report and recommendations.

DESCRIPTION

The property refered to in this report is the left hand section of an older and larger original property new split into two houses. The ground floor walls being stonework and the upper section being half timbering with stonework between the panels and rendered

CESEEVASTONS

Some evidence of repair in the past to the timbering where water has been absorbed over the years. Old apparently inactive infestation by Anobium Punctatum to external timbers with scattered active infestation in some places to internal timbers

Where visible evidence of Anobium Punctatum is present treatment should be carried out. two small sections of plaster will have to be removed to allow treatment to part of the roof.

GROUND FLOOR

TREATMENT

Front centre room Wood block floors no apparent evidence to the floors Mederate active infestation by Anobium Punctatum to the pass door of front room also panelling on front wall

Treatment "C" to pass door and panels. Inject flight holes and surface application. No treatment to floors.

Hall

Rear Left room Selid floor

No treatment

Stairs (to first floor) No wisible evidence

No treatment

FIRST FLOOR

5. Front right room (exposed joists below) A slight scattered active infestation by Anobium Purctatum to the floor

Top durface application and treat the joists and beams from below.

TREATMENT

- 6. Front left room
- 7. Lending
- 8. Left centre room
 Old apparently inactive heavy infestations together with
 slight scattered active infestation by Anchium Punctatum
 to the floors.

Freatment A

9. Left bathroom and Toilet
Limited inspection due to floor coverings.

No treatment

10. Rear left room
Slight to moderate scattered active infestation
by Akebium Functatum to the floor

Treatment A

11. Exposed heavy section internal timbers & panelling Old apparently imactive infestation together with slight scattered active infestation by Apolium Phnetatum

Treatment 'C' throughout with surface treatment to penelling

A moderate to heavy scattered active infestation by Anobium Fractatum

Treatment 'B'

TOP FLOOR AREA

A moderate scattered active infestation by Ambium Punctatum to the floor.

Treatment *A*

14. Heavy section exposed internal timbers
A moderate scattered active infestation by Anobium
Punctatum.

Prestment 'C' throughout

A limited inspection due to plasterwork but where seen a moderate scattered active infestation by Anobius Punctatum.

Preatment 'D' Remove sections of plaster approx 12" strips between trusses to allow treatment

The subsequent making good of plaster is to be carried out by clients own plasterer as a seperate item.

OUR ESTIMATE FOR THE TREATMENT AS STATED AS #366.0s.od.

Should our estimate be acceptable, we would ask you to kindly sign the enclosed Acceptance Form and return same to this office, together with any instructions as to when you would require the work corried out.

If you require any further assistance, please do not hesitate to contact us.

Yours feithfully PLAD TIMBER PRESERVATION SPECCIALISTS LIMITED